

PRODUCT/SERVICE BULLETIN

Date: ____2/7/2022___


Bulletin Number: _PB-0002_____

BUMPER BOTTOM FLANGE CONDITIONS

- Valley Chrome's bumper bottom flanges (the underside of bumpers that faces ground when installed on a truck) are not fully finished.
- Polishing the bottom flanges would add significant cost to our production process, add lead time to manufacturing and would result in higher product costs to dealers and distributors.
- The bottom flanges are not seen from a standard viewing location on trucks after installation.


The following conditions are normal and are not warranted:





Plating rack hole touchup & Plating rack hole discoloration





Typical **TOP** flange shown here. Top flanges are warranted for a highly polished finish, unlike bottom flanges.

